


GM Gen. 2 6T70, 6T75, 6T80

sonnax®

2 Imtec Lane • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

Click on Sonnax part numbers to see more information.

1 124740-14K Oversized TCC Control Valve Kit




Helps cure:

- Excess TCC slip • Low cooler flow
- Overheating • TCC apply & release concerns

Note: Requires tool kit F-124740-TL14 & the VB-FIX reaming fixture.

2 124740-24K Oversized TCC Regulator Valve Kit



Helps cure:

- Code P0741 • Code 742
- Harsh TCC apply • TCC slip

Note: Requires tool kit F-124740-TL24 & the VB-FIX reaming fixture.

3 124740-03K Isolator Valve Kit



Helps cure:

- Low line pressure • No line rise
- Line pressure instability • Burnt clutches

4 124740-16 Isolator Valve Spring

5/Bag


Helps cure:

- No line rise
- Line pressure instability

5 124740-57K 4-5-6 Accumulator Piston Kit

Helps cure:

- 3-4 Flare • Ratio codes
- 4-5-6 Clutched Burned • Slipping gears



6 124740-48K Oversized AFL Valve Kit




Helps cure:

- Solenoid performance codes
- Wrong gear starts • Clutch failure

Note: Requires tool kit F-124740-TL48 & the VB-FIX reaming fixture.

7 124740-56 Oversized Clutch Boost Valve



Fits Any of 3 Locations

Helps cure:

- Shift quality is not load sensitive
- Harsh shifts • Slips & flares


Note: Requires tool kit F-144740-TL22 & the VB-FIX reaming fixture.

8 124740-02K O-Ringed End Plug Kit

Helps cure:

- Pressure loss • Shift concerns
- Burnt clutches • TCC apply concerns

9 124740-60K Oversized Pressure Regulator Valve Kit



Helps cure:

- Erratic line pressure • Poor shift quality
- Burnt Clutches • Low converter & lube flow

Note: Requires tool kit F-124740-TL60 & the VB-FIX reaming fixture.



Zip Kit®
6T70-G2-ZIP

This Sonnax kit is also available, see www.sonnax.com for details.