Toyota/Lexus



(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com



This Sonnax kit also is available. see www.sonnax.com for details

A340-LATE-ZIP A340E/F Type 3 & 4 Only

(6) 97855-30K

Type 1 (8931 Casting Code) with .546" Dia. Large Spool Only

(6) 97855-23K

Boost Valve Kit

Boost Valve Kit

Type 1 (8931 Casting Code) with .566" Dia. Large Spool Only

97741-01K

Dual-Ratio Boost Valve Kit

Type 3 & 4 Only

Helps cure:

- Delayed engagement
- Low line rise
- Low line pressure in Reverse

(8) 97741-19K

O-Ringed End Plug Kit

Type 3 & 4 Only

Helps cure:

- Soft shifts
- Low line rise
- Slips & flares


Note: Includes seven end plugs in various sizes. Follow usage chart included in instructions to determine correct location and size of O-ringed end plug.

(9) 97855-24K


Type 1 (8931 Casting Code) Only

(10) 97741-10K

A340E/F Type 3 & 4 with .353"









Helps cure:

- Low line pressure
- High line pressure
- Poor shift quality

Note: Both 97741-06K and 97741-10K kits require tool kit F-97741-TL6 & the VB-FIX reaming fixture.

Click on Sonnax part numbers to see more information.



(1) 77741-02K

Lockup Relay Control Valve Kit

A340E/F Type 3 & 4 Only

Helps cure:

- TCC apply & release concerns
- TCC codes
- RPM fluctuation
- (2) 97741-20K





A340E/F Type 3 & 4 Only

(3) 97855-27K

Lockup Relay Valve Sleeve Kit

Type 1 (8930 Casting Code) Only

Helps cure:

- TCC apply & release concerns
- TCC codes
- Inadequate lubrication

Note: Requires tool kit F-97741-TL20 & the VB-FIX reaming fixture.

(4) 97741-17K



Type 1 (8930 Casting Code) Only

(5) 97741-18K

A340E/F Type 3 & 4 Only





Oversized Secondary Pressure Regulator Valve Kits

Helps cure:

- TCC apply & release concerns
- Burnt TCC apply components
- Overheated transmission

Note: 97741-17K Requires tool kit F-39741-TL11, 97741-18K Requires tool kit F-97741-TL18* & they both requrire the VB-FIX reaming fixture.

